




Ice**SLEET** X5

Quick Start Guide

Iceberg-Thermal.com

Box Content

A



x 1

B



x 4

C



x 1

AMD

D




x 4

E



x 4

F



x 2


Intel

G



x 4

H




x 2

I



x 4

J



x 1


AMD

AM4


B



F



D




AM3(+)/AM2(+)/FM2(+)/FM1


B



F




E




AMD


AM4



AM3(+)/AM2(+)/ FM2(+)/FM1



AMD




INTEL

LGA 2066/2011(-v3)


B



H



G




LGA 1200/115X/1366/775

B




H



I




J




INTEL

H




J




INTEL

LGA 2066/2011(-v3)




INTEL

LGA 1200/115X/1366/775




INTEL


LGA 1200/115X/1366/775




Step 1




Step 2




Step 3




Step 4




Step 5



Step 6



Step 7



Step 8

